

$$F(x) = ADE_0 \left[ 1.25 \left( \frac{3}{4} \right)^{\frac{3}{4}} + 50 \left( \frac{5}{4} \right)^{\frac{1}{4}} \right]$$

$$D = 2.875 \text{ in.}$$

$$d = 1.32 \text{ in.}$$

$$E_0 = 3000 \text{ psi}$$




FIGURE 3